

Assessment of Wood Pile Deterioration due to Marine Organisms

Roberto Lopez-Anido, M.ASCE¹; Antonis P. Michael, S.M.ASCE²; Barry Goodell³; and Thomas C. Sandford, M.ASCE⁴

Abstract: In this paper a description of the major groups of marine organisms causing significant wood pile damage is presented. These organisms are divided into two groups: (1) fungi and (2) marine borers. The basic physical and biological characteristics of these organisms are presented, as well as the type of damage that they cause in marine wood piles. The objective of the study presented in this paper is to characterize deterioration of wood piles due to marine organisms and to assess damage in the wood pile zones of a typical waterfront installation. Marine borer activity in Maine coastal waters is assessed through a survey directed to harbor masters; the results of the survey are correlated with historic data. In order to illustrate the type and extent of wood pile deterioration, two case studies in Maine harbors are presented.

DOI: 10.1061/(ASCE)0733-950X(2004)130:2(70)

CE Database subject headings: Piles; Wood; Fiber reinforced plastics; Fiber composites; Wooden structures; Deterioration.

Introduction

The problem of deterioration of wood piles due to marine organisms dates back to the historic use of wood in piers and other waterfront facilities. Even though wood pile deterioration has been mitigated to some extent with the use of preservative treatments, it still remains a concern. Some of the chemicals used for wood preservation have been linked to human health concerns and, therefore, their use has been restricted. For these reasons, waterfront owners are looking for alternative solutions for wood pile protection.

There are two major groups of organisms that deteriorate wood in waterfront structures. Wood degrading fungi generally attack above the water-line region where adequate oxygen allows them to survive and decay the wood. Marine borers attack a variety of wood substrates but are only found in marine environments. Some marine borer species are not of concern from the standpoint of marine piers and waterfront facilities, but aggressive attack by these organisms will occur particularly in temperate marine waters. These two groups of organisms attack the wood in

different zones of a waterfront pile. Fungi are typically found above the waterline, while marine borers primarily attack wood that is submerged or in the tidal zone.

Wood-boring organisms found in saltwater that cause damage to wood piles can be classified as: (1) molluscan borers (shipworms and pholads); and (2) crustacean borers including multiple species commonly known as gribbles (Goodell 2000). Both shipworms and gribbles attack the wood piles for shelter and, at least in the case of shipworms, wood can also be digested through the aid of microbial symbionts (Goodell 2000) to supplement filter feeding nutrition.

Studies conducted in Maine over a period of 23 years (1936–1959) using wood test boards revealed problems associated with shipworms during certain years and at specific geographic locations (Wallour 1959). *Limnoria* spp. were present in Maine waters every year during the period studied and caused significant damage.

Understanding the cause and characterizing the extent of wood pile deterioration is the first step in designing a repair method for damaged piles, as well as in devising a protection strategy to prevent further attack from marine organisms. For example, a system for structural restoration of wood piles with fiber reinforced

polymer (FRP) composite shells was designed based on this approach (Lopez-Anido et al. 2004b). This system provides shear transfer capability between the wood pile and the encasing FRP composite shells, which strengthens the damaged pile portion (Lopez-Anido et al. 2003, 2004a). The repair system can also reduce the rate of future deterioration by introducing a barrier that protects the wood pile from marine borer attack.

The objective of the study described in this paper is to characterize the deterioration of wood piles due to wood deterioration organisms and to assess damage in the microenvironment zones of a typical waterfront installation. An early study of marine borer activity in Maine waters is reviewed. The results of a recent survey of wood pile deterioration in Maine harbors are discussed. Two case studies in Maine harbors that illustrate typical gribble and shipworm damage are presented.

¹Assistant Professor, Dept. of Civil and Environmental Engineering and Advanced Engineered Wood Composites Center, Univ. of Maine, Orono, ME 04469-5711 (corresponding author). E-mail: rla@maine.edu

²Graduate Research Assistant, Civil and Coastal Engineering Dept., Univ. of Florida, Gainesville, FL 32611.

³Professor, Wood Science and Technology and Advanced Engineered Wood Composites Center, Univ. of Maine, Orono, ME 04469-5711.

⁴Associate Professor, Dept. of Civil and Environmental Engineering, Univ. of Maine, Orono, ME 04469-5711.

Note. Discussion open until August 1, 2004. Separate discussions must be submitted for individual papers. To extend the closing date by one month, a written request must be filed with the ASCE Managing Editor. The manuscript for this paper was submitted for review and possible publication on August 1, 2002; approved on March 19, 2003. This paper is part of the *Journal of Waterway, Port, Coastal, and Ocean Engineering*, Vol. 130, No. 2, March 1, 2004. ©ASCE, ISSN 0733-950X/2004/2-70-76/\$18.00.

Review of Wood Pile Deteriorating Organisms

Fungi

Wood decay fungi are found growing either as parasites on living trees or as saprophytes on the dead remains of the trees (U.S. Army et al. 1978). Fungi can reproduce by means of microscopic spores, which can be single or multicellular, and in many cases wood degrading fungi can be spread through dissemination of mycelial fragments. Brown rot decay is the most common type of decay occurring in coniferous wood species and in early stages of attack the wood will have lost a limited amount of weight and can appear visually to be sound, yet have lost as much as 70% of modulus of elasticity and modulus of rupture (Wilcox 1978). In advanced decay stages physical and chemical changes have occurred which can be noted in features such as: (1) Change of color—advanced decay of wood by fungi is almost always accompanied by a change in color of the attacked wood (Cartwright and Findlay 1958; Kelly 1999; Goodell et al. 2003); (2) softening—the area where decay fungi have attacked appears to be soft in texture in advanced decay stages (Cartwright and Findlay 1958; Kelly 1999; Goodell et al. 2003); (3) change in density—as the wood is decayed it loses mass. Wood in advanced stages of fungal decay will be extremely light when the wood is dry; (4) change in odor—wood attacked by fungi will often have a mushroom like smell, or other uncharacteristic odor, but the presence of this smell does not necessarily mean that decay is present; and, (5) in brown rot the wood will develop checking, or a cracked appearance, perpendicular with the grain. Once these advanced decay features are present, the wood is normally beyond the stage where remediation can be applied to control the decay and removal and replacement of the wooden member is required.

Most wood decay fungi cannot survive submerged in water because the high moisture content excludes the levels of oxygen required for their growth. Yet they do require moist wood, above 30% moisture content, to be active and degrade the wood. It has been found that some fungal species can grow in the above-water portion of wood piles submerged in saltwater. The portion of the wood pile that is in the atmospheric zone is less affected by saltwater, but still is wetted by freshwater precipitation. This creates favorable conditions for the growth of conventional fungi (brown or white rot) that can cause considerable damage (U.S. Army et al. 1978).

Molluskan Borers: Shipworms

One of the families of shipworms is the family of Teredinidae, which includes *Teredo* spp. and *Bankia* spp. This type of marine borer has a modified shell (valves) that does not fit around the body of the animals as occurs in clams (Abood et al. 1995; Goodell 2000). *Teredo* spp. is a wormlike borer with a gray body that produces a shell-like material to line its burrow (Chellis 1961; U.S. Army 1990). Modified small shells at the anterior end form a pair of abrasive plates that are used to burrow into the wood, producing wood particles that are ingested. External evidence of attack is hard to find because small siphons are the only portions extending to the wood surface. Initially *Teredo* spp. larvae begin excavation with a 0.5–3 mm diameter hole. The borer can extend its tunnel along the grain (Goodell 2000). The length of this type of marine borer varies ranging from 150 mm to 1.8 m length and diameters up to 25 mm (Chellis 1961). The length of the tunnels depends on the extent of the attack. When the attack is extensive,




Fig. 1. *Teredo navalis* (courtesy of Gillis, personal communication, 2002)

the tunnels become crowded and their length and diameter may be limited. The white shell-like material lining the tunnels can be found mixed with shavings if the wood is bored with a drill during inspection (Highley 1999). Cellulosic portions of the wood are digested with the help of bacterial symbionts. Borer activity will turn the wood into a honeycomb-like matrix, which will lead to a severe reduction in strength even though the outer portion of the pile appears sound (Goodell 2000). A picture of *Teredo navalis* is shown in Fig. 1, where the arrows point to the valves that have been modified for boring through wood (Gillis, personal communication, 2002). *Bankia* spp. is very similar to *Teredo* spp., but is usually larger (Chellis 1961). *Bankia* spp. is shown in Fig. 2. Typical shipworm damaged wood pile sections extracted from Belfast Harbor, Me., are shown in Fig. 3.

Molluskan Borers: Pholads

Borers, such as *Martesia* spp. and *Xylophaga* spp., belong to the Pholadidae (pholads) family. They are similar to shipworms in the sense that they are also mollusks. The adult body of pholads, unlike shipworms, remains loosely surrounded by shells as it grows in its burrow (Highley 1999). Pholad shells do not fit tightly but they have ridges which function as rasps for burrowing. Pholads also have up to four external plates in addition to the two primary plates covering their soft body parts. When pholads die, remnants of the primary plates can remain in the burrow. Although pholads are particularly aggressive in tropical waters, deepwater species can operate in cold waters causing extensive damage to wood. The length of pholad tunnels is relatively short




Fig. 2. *Bankia* spp. (courtesy of Wilson, personal communication, 2001)




Fig. 3. Typical shipworm damage, Belfast, Me.

(up to 60–70 mm) and their diameters are up to 25 mm. The tunnel opening can often be smaller than the diameter of the borer (Chellis 1961; Goodell 2000).

Crustacean Borers: Gribbles

Limnoria lignorum is one species of *Limnoria* spp., which are also known by the common names “gribbles” and “sea lice.” Gribbles resemble the wood louse and have a length between 3 and 6 mm. Their width ranges from one third to one half of their length. They are often slipper shaped with horny boring mandibles, two sets of antennae and seven major sets of legs. Their legs are equipped with sharp hooked claws to grip the wood. Gribbles can roll themselves into a ball, swim, crawl, and jump (Chellis 1961). Gribbles can swim throughout their lives and they can leave or be dislocated from wood being attacked and return to




Fig. 4. *Limnoria* spp. damaged wood

tunnel at another location. They commonly attack in coastal regions making shallow burrows in the surface of the wood (Johnson 2002) as shown in Fig. 4. When large numbers of gribbles attack, only a thin layer of wood is left between the burrows. The action of the waves and tidal currents wash away these thin layers exposing new surfaces for the gribbles to attack. This causes extensive thinning of the wood section. In wood piling, the damage caused by gribbles is typically greater in the tidal zone (Chellis 1961).

Damage Zones in Wood Piles

Wood piles that support piers or other marine structures are driven into the mud and extend above the waterline to the deck or structure they support. The vertical variation of exposure conditions of the wood pile has previously been delineated into different microenvironment zones by the U.S. Army Corps of Engineers and allied organizations (U.S. Army Corps of Engineers et al. 2001). The microenvironment variation affects the type and the extent of damage produced by marine organisms. Wood pile damage at the mudline observed in Portland Harbor, Me., is shown in Fig. 5(a). A typical damage profile in the different zones of a wood






Fig. 5. (a) Wood pile at mudline in Portland Harbor, Me.; (b) typical damage profile of wood pile



(a)




(b)

Fig. 8. Typical wood test board results adapted from Wallour (1959): (a) *Teredo* spp., Searsport, Me.; and (b) *Limnoria* spp., Portland, Me.

tional extent of marine borer damage; (2) recent changes in the amount of marine borer attack; and (3) type of marine borer organism. The survey results revealed problems with shipworm damage in wood piles at the same geographic locations in Maine coastal waters reported 41 years earlier (Wallour 1959).

First Case Study: Wood Pile Deterioration in Portland Harbor, Me.

The condition of structural wood piles in Portland Harbor piers was visually assessed in May 2000. The objective of the inspection was to determine the type and extent of damage in structural wood piles. Wood pile damage in two piers was inspected during low tide: Portland Pier and Custom House Wharf, as shown in Lopez-Anido et al. (2004b).



(a)

(b)

Fig. 9. (a) Typical *Limnoria* spp. damage, Portland, Me.; (b) damaged piles, Portland, Me.

The Portland Pier has a timber retaining wall with solid fill, wood piles, and a wood deck supporting a parking lot [Maine Department of Transportation (DOT) 1986]. The Custom House Wharf is an earth-filled pier structure with wooden-timber and a steel crib bulkhead, wood piles, and an asphalt paved wood deck. There are several marine-related businesses operating on the pier (Maine DOT 1986).

Damage was observed at the Portland pier in several wood piles, as shown in Figs. 9(a and b). In some cases, a loss of cross section (necking in the intertidal zone) up to 70% was observed. It was observed that several old damaged piles were left in place, and new wood piles were driven nearby. In other cases the old damaged piles were cut off, and a new pile portion was spliced on top.

The observations made at the Custom House Wharf were similar to the ones made at Portland Pier. Several piles had reduced cross-sections in the tidal zone between low and high tide. Other piles had extensive visible damage at the butt (reduction in cross section), as well. One wood pile was measured at two locations: The diameter at the butt was 254 mm, and the diameter at the mud line level (1.83 m below the butt) was only 165 mm. This loss of cross section represents about a 50% reduction in the cross

Table 1. Survey Responses on Traditional and Recent Marine Borer Attacks in Maine

City or town harbor (from south to north)	Traditional extent of marine borers damage	Change in relative amount of attack in recent years	Type of marine borer
Boston (out-of-state correlation)	Moderate	No	<i>Limnoria tripunctata</i>
York, Me.	Nonexisting	No	Unknown
Wells Harbor, Me.	Nonexisting	No	Unknown
Kennebunk, Me.	Unknown	No	Gribbles
Portland, Me.	Moderate	No	<i>Teredo</i>
Falmouth, Me.	Nonexisting	No	Unknown
Georgetown, Me.	Nonexisting	No	Unknown
Wiscasset, Me.	Moderate	No	Gribbles
Saint George, Me.	Moderate	No	<i>Teredo</i> and Gribbles
Rockland, Me.	Nonexisting	No	Unknown
Belfast, Me.	Nonexisting	Yes	<i>Teredo</i>
Searsport, Me.	Moderate	Yes	Unknown
Castine, Me.	Nonexisting	No	Unknown
Mount Desert, Me.	Nonexisting to moderate	No	Unknown




Fig. 10. Wood piles with shipworm damage extracted from Belfast Harbor, Me.

sectional area. To assess the condition of a wood pile below the mud line, a hole of approximately 130 mm in depth was excavated in the surrounding soil. Visual inspection indicated that the wood pile had no reduction in cross section or any apparent damage below the mud line. This observation confirms previous findings on the condition of extracted wood piles from the Portland Harbor. In general, the wood pile damage observed in Portland Harbor was attributed to *Limnoria* spp. This finding is in agreement with an earlier report (Wallour 1959). No internal coring or inspection was performed to determine if shipworm damage had also occurred; however, visual inspection of the areas of reduced cross section revealed no shipworm boring.

Second Case Study: Wood Pile Deterioration in Belfast Harbor Municipal Pier, Me.

Structural wood piles that had been damaged by marine borers were inspected in September 2000 by a team of scientists and engineers from the University of Maine. The wood piles inspected at Belfast Harbor were untreated white oak and had been in service for approximately 1–1 1/2 years.

Wood fender piles with diameters up to 380 mm that were extracted from the harbor revealed severe damage from shipworms. Typical shipworm damage to the wood piles extracted from the harbor is shown in Figs. 10(a and b). Although casual visual inspection of the wood pile exterior showed no evidence of deterioration, the interior of the piles was severely deteriorated. The density of the channels made by the borers indicated a very large infestation of shipworms. The individual borers channeled into the pile interior riddling the intertidal portion of the piles completely. The borers did not turn to orient along the grain nor did they reach their mature length because of the heavy attack which limited the space and time for the shipworms to extend to their full potential. The severity of this attack was surprising but perhaps not unique. In colder waters such as those typically found on the coast of Maine, marine borer attack is normally much slower in more temperate waters. No evidence of extensive marine borer attack in several years prior to the year 2000 had been reported by marinas in the Belfast area. Yet the borers were able to completely riddle the dense wood oak in as little as one year in 2000. The following year, again evidence of severe marine borer infestation was lacking in the Belfast harbor. It is unknown why the sporadic type of attack occurs, but similar patterns of attack have been noted previously in Maine and other eastern seaboard marine waters (Wallour 1959). It is also unknown, given the relatively low level of activity of marine boring in the years preceding and following an aggressive attack year, how the organism

can build up its larval population so quickly in the bay, or why the large population would either die off or be unsuccessful in colonization in succeeding years.

The short time span and the extent of the marine borer damage illustrate the importance of protecting wood piles or providing the means to repair such structures. It is worth noting that the solution adopted to replace the deteriorated wood piles in Belfast Harbor was to import from Venezuela a naturally-durable tropical wood called Greenheart (Griffin 2003). However, the exploitation of tropical woods is not a sustainable solution for marine pier protection and results in the “exportation” of environmental concerns in the U.S. to other countries for solution.

Conclusions

Based on the survey of information presented in this paper, the following conclusions are drawn:

1. There is a serious problem with marine pile deterioration specifically in the state of Maine and generally along the coastal waters of the United States. This problem is not new, and it is sometimes sporadic, as the results from wood board tests conducted as far back as the 1940s show. The sporadic nature of some marine borer activity does not mean that this problem can be ignored since the rapid, aggressive attack requires protection of piles for the worst case conditions. Both shipworms and gribbles were found to cause significant wood pile damage in Maine waters.
2. The presence of shipworms at specific geographic locations in Maine coastal waters and their aggressiveness contradicts the general preconception that shipworms are not active in cold waters.
3. Field observations indicate that marine borer organisms need to be characterized to understand the potential and nature of wood pile attack. Furthermore, classification of damage zones in wood piles serves not only to assess damage but also to develop a protection strategy.

Acknowledgments

Partial funding for the study presented in this paper was provided by the National Oceanographic and Atmospheric Administration, U.S. Department of Commerce, through the Sea Grant College Program Award Nos. NA96RG0102 and NA16RG1034, and by the National Science Foundation through the CAREER Grant No. CMS-0093678.

References

- Abood, K. A., Ganas, M. J., and Matlin, A. (1995). “The Teredos are coming!” *Proc., Ports '95 Conf. on Port Engineering and Development for the 21st Century, Part 1*, Tampa, Fla., 677–690.
- Cartwright, K. St. G., and Findlay, W. P. K. (1958). *Decay of timber and its prevention*, Forest Products Research Laboratory, Her Majesty's Stationary Office, 2nd Ed., London.
- Chellis, R. D. (1961). “Deterioration and preservation of piles.” *Pile foundations*, McGraw-Hill, New York, 339–372.
- Coburn, S. K. (2000). “Corrosion factors to be considered in the use of steel piling in marine structures.” *Pile Buck*, Technical Guidelines, Palm City, Fla., 10A–18C.
- Goodell, B. (2000). “Wood products: deterioration by insects and marine organisms.” *Encyclopedia of materials science and technology*, Elsevier, New York.

- Goodell, B., Nicholas, D., and Schultz, T. (2003). *Wood deterioration and preservation: advances in our changing world*, American Chemical Society Series, Oxford Univ. Press, New York.
- Griffin, W. (2003). "Belfast dredging nears completion." *Bangor Daily News*, April 14, 3.
- Highley, T. L. (1999). "Biodeterioration of wood." *Wood handbook—wood as an engineering material*, USDA, Chap. 13, Forest Products Laboratory, Madison, Wis.
- Johnson, B. R. (2002). "Of shipworms and gribbles, pillbugs, and pholads." *AWPA Newsline*, Newsletter, April-May, 4–6.
- Kelly, S. W. (1999). "Underwater inspection criteria," *Rep.*, Naval Facilities Engineering Service Center, Port Hueneme, Calif.
- Lopez-Anido, R., Michael, A. P., and Sandford, T. C. (2003). "Experimental characterization of FRP composite-wood pile structural response by bending tests." *Mar. Struct.*, 16(4), 257–274.
- Lopez-Anido, R., Michael, A. P., and Sandford, T. C. (2004a). "FRP composite-wood pile interface characterization by push-out tests." *J. Compos. Constr.*, in press.
- Lopez-Anido, R., Michael, A. P., Sandford, T. C., and Goodell, B. (2004b). "Repair of wood piles using prefabricated FRP composite shells." *J. Perform. Constr. Facil.*, in press.
- Maine Department of Transportation (DOT). (1986). "Port inventory and evaluation," *Rep.*, Vol. I, Augusta, Me.
- U.S. Army. (1990). "Chapter 8—Pile wharves." *Field manual—port construction and repair*, Publication No. FM 5-480, U.S. Army, Fort Leonard Wood, Mo.
- U.S. Army, U.S. Navy, and U.S. Air Force. (1978). "Chapter 2—Timber structures." *Maintenance of waterfront facilities*, Publication Army TM 5-622, Hyattsville, Md, 2.1–2.14.
- U.S. Army Corps of Engineers, Naval Facilities Engineering Command, and Air Force Civil Engineering Support Agency. (2001). "Chapter 5—Inspection." *Unified facilities criteria (UFC)—Operation and maintenance: Maintenance of waterfront facilities*, Publication No. UFC 4-150-07, Washington, D.C.
- Wallour, D. B. (1959). "13th progress report on marine borer activity in test boards operated during 1959." *Rep. No. 11466*, William F. Clapp Laboratories, Duxbury, Mass.
- Wilcox, W. W. (1978). "Review of literature on the effect of early stages of decay on wood strength." *Wood Fiber Sci.*, 9(4), 252–257.